

INTRODUCTION	
SCOPING REPORT	1.1
SCOPING OPINION	1.2a
SCOPING COMMENTS	1.2b
EA RESPONSE	1.2c
AIR QUALITY	
ENVIRONMENTAL PROTECTION UK – DEVELOPMENT CONTROL:	8.1
PLANNING FOR AIR QUALITY	
JUNCTION ANALYSIS TRAFFIC DATA	8.2
NOISE	
GLOSSARY OF ACOUSTIC TERMINOLOGY	9.1
TECHNICAL SURVEY METHODOLOGY AND MEASUREMENT RESULTS	9.2
TRAFFIC DATA FOR THE NOISE ASSESSMENT	9.3
TECHNICAL DEMOLITION AND CONSTRUCTION PLANT USED FOR NOISE PREDICTIONS	9.4
LANDSCAPE	
TREE REPORT	10.1
LIGHTING ASSESSMENT	10.2
VIEWPOINTS	10.3
ARCHEOLOGY AND CULTURAL HERITAGE	
LIST OF CONSULTED MAPS	11.1
AERIAL PHOTOGRAPHIC ASSESSMENT	11.2
HISTORIC BUILDING RECORD	11.3
ARCHAEOLOGICAL DESK BASED ASSESSMENT	11.4
THE KNOWN AND RELEVANT ARCHAEOLOGICAL RESOURCE	11.5
ARCHAEOLOGICAL EVALUATION	11.6
ECOLOGY	
PHASE 1 TARGET NOTES	12.1
SUMMARY OF CONSTRUCTION PHASE POTENTIAL IMPACTS	12.2
AA SCREENING	12.3
NE RESPONSE TO AA	12.4
GROUND AND GROUNDWATER CONDITIONS	
PHASE 1 ENVIRONMENTAL ASSESSMENT	13.1
PHASE 1 UNDEVELOPED LAND	13.2
PHASE 2 NORTHERN DEVELOPMENT SITE	13.3
PHASE 2 HOTEL	13.4
WALDRINGFIELD PIT SSSI	13.5
NE LETTER	13.6

WATER

ADASTRA PARK FRA	14.1
CONSULTATION LETTERS	14.2

AGRICULTURE

ANALYTICAL REPORT	15.1
AGRICULTURAL LAND CLASSIFICATION	15.2